


VEHICLE IDENTIFICATION NO.

JN1BY1AR1BM375348



2011 Infiniti M37

Sedan/Saloon

3.7 L

Gasoline

4WD/4-Wheel Drive/4x4

VEHICLE IDENTITY

VIN	MODEL YEAR	MAKE
JN1BY1AR1BM375348	2011	Infiniti
MODEL	TRIM	SERIES
M37	-	-
BODY CLASS	VEHICLE TYPE	DOORS
Sedan/Saloon	PASSENGER CAR	4
WMI	REGION OF ORIGIN	VIN PATTERN
JN1	Japan	JN1BY1AR*BM

ENGINE & DRIVETRAIN

CYLINDERS	DISPLACEMENT	HORSEPOWER
6	3.7 L	-
CONFIGURATION	ENGINE MODEL	VALVETRAIN
V-Shaped	-	-
FUEL TYPE	DRIVE TYPE	TRANSMISSION
Gasoline	4WD/4-Wheel Drive/4x4	-
GEARS		
-		

MANUFACTURING & PLANT

MANUFACTURER	PLANT COMPANY	PLANT CITY
NISSAN MOTOR COMPANY, LTD	Tochigi Plant	TOCHIGI
PLANT STATE	PLANT COUNTRY	GVWR
KAMINOKAWA	JAPAN	Class 1: 6,000 lb or less (2,722 kg or less)

FACTORY SAFETY EQUIPMENT & DRIVER ASSISTANCE

TIRE PRESSURE MONITORING
Direct

AIRBAGS & RESTRAINT SYSTEMS

FRONT AIRBAGS

1st Row (Driver and Passenger)

SIDE AIRBAGS

1st Row (Driver and Passenger)

CURTAIN AIRBAGS

1st and 2nd Rows

SEAT BELT TYPE

Manual

OTHER RESTRAINTS

2nd row outboard and 3-pt manual belts, 2nd row center 3-point manual belts

ADDITIONAL FACTORY SPECIFICATIONS

CAB TYPE

-

EPA FUEL ECONOMY & ENVIRONMENT

18

CITY MPG

21

COMBINED MPG

26

HIGHWAY MPG

EST. ANNUAL FUEL COST

\$3,800/yr

EPA SMOG RATING (1-10)

5

GREENHOUSE GAS SCORE (1-10)

-

CO2 TAILPIPE

423 g/mi

EPA SIZE CLASS

Midsize Cars

EPA record: 2011 INFINITI M37 - Auto (S7), 6 cyl, 3.7 L

FEDERAL SAFETY RECORD

36

COMPLAINTS

1

RECALLS

0

INVESTIGATIONS

99

SERVICE BULLETINS

Complaint precision: 17 of the 32 complaints that identified a VIN were filed for this VIN's exact configuration (matching first 8 VIN characters).

OPEN RECALLS

Recall data could not be loaded when this report was generated.

FEDERAL DEFECT INVESTIGATIONS

0

No federal defect investigations are on file for this vehicle.

TECHNICAL SERVICE BULLETINS

99

99 manufacturer communications are on file with federal safety regulators for this vehicle. Service bulletins describe known issues and repair procedures dealers receive from the manufacturer. The 3 most recent:

ITB09-063C · Apr 13, 2026 · STRUCTURE

CERTIFICATION LABEL AND VIN PLATE REPLACEMENT SERVICE INFORMATION Because of collision damage or other vehicle repair, a replacement "Certification Label" or "VIN Plate/Label" may be needed. HINT: Certification Label = F...

ITB10-029C · May 20, 2024 · ELECTRICAL SYSTEM

CAN COMMUNICATION CODES - DIAGNOSTIC TIPS AND GUIDELINES This bulletin has been amended. See AMENDMENT HISTORY on the last page. Please discard previous versions of this bulletin.

ITB13-052E · May 20, 2024 · ELECTRICAL SYSTEM

INTELLIGENT KEY NOT DETECTED / ENGINE WILL NOT START This bulletin has been amended. See AMENDMENT HISTORY on the last page. Please discard previous versions of this bulletin.

SAFETY RATINGS

Overall	★★★★☆	Frontal Crash	★★★★☆
Frontal - Driver	★★★★★	Frontal - Passenger	★★★★☆
Side Crash	★★★★★	Side - Driver	★★★★☆
Side - Passenger	★★★★★	Side Pole	★★★★★
Rollover	★★★★☆		

Rollover probability: 11.3%

Stability Control: Standard

Forward Collision Warning: Optional

Lane Departure Warning: Optional

Rated on the U.S. government 5-Star Safety Ratings program (5 = best).

OFFICIAL CRASH TEST PHOTOS



FRONTAL CRASH TEST

Official U.S. government crash-test photography (public domain).



SIDE CRASH TEST



SIDE POLE CRASH TEST

OWNER COMPLAINTS

36 FILED

4 CRASH-RELATED

2 INJURIES

POWER TRAIN · ENGINE · FORWARD COLLISION AVOIDANCE

Dec 22, 2025

CRASH

im the dealer sold my the car or maker uncertain problem

AIR BAGS

Nov 8, 2021

The Air Bag Warning Light on the dash blinks continuously and the Front Passenger Air Bag Status Light remains on whether or not the seat is occupied. I took the car to the Infiniti dealer. The Service Advisor said the Occupant Classification System Control Unit or OCS sensor needs to be replaced but Infiniti no longer...

POWER TRAIN

Dec 6, 2020

VEHICLE HAS HESITATION DURING ACCELERATION, IT LAGS AND TRANSMISSION IS UNRESPONSIVE MOST OF THE TIMES. THERE ARE OTHER TIMES THAT THE VEHICLES TRANSMISSION WILL DOWNSHIFT AND REV UP WHILE COASTING DOWN HILL WHILE FOOT IS OFF ACCELERATOR. VEHICLE ONLY HAS 59K MILES ON IT AND SHOULD NOT BE HAVING THIS ISSUE. IT'S LIKE T...

POWER TRAIN

Sep 3, 2020

THE CAR HESTITATES, JERKS, REVS AT LOW SPEED, ROUGH IDLING, AND SLOW ACCELERATION. I REPLACED THE MAF SENSOR B 4 MONTHS AGO AFTER MY CAR ENGINE LIGTH CAME ON WHILE ON THE HIGHWAY AND I COULDNT ACCELERATE PASS 30 MILES PER HOUR.I HAD TO PRAY AND DRIVE TO THE NEAREST PLACE FOR THEM TO FIX IT.

STEERING

Feb 26, 2020

I'D LIKE TO REPORT A PROBLEM THAT HAS OCCURRED WITH MY 2011 INFINITI M37 WHICH SEEMS TO BE PRETTY FATAL. THE PLASTIC COVER THAT COVERS THE STEERING WHEEL'S ROD CRACKS OPEN WHEN THE STEERING WHEEL IS TILTED TO A LOWER POSITION. ONCE THE COVER IS CRACKED, STEERING WHEEL RUBS ON TO THE PLASTIC BEHIND IT AND MAKES THE STEE...

STEERING · VEHICLE SPEED CONTROL · ELECTRONIC STABILITY CONTROL (ESC)

May 11, 2019

I HAVE SEVERAL ISSUES. THE STEERING WHEEL PEELS. I HAVE A CRACKED DRIVER'S SIDE LEATHER INTERIOR DOOR. THE CAR STARTED JERKING REALLY BAD ON A CITY STREET, I COULDN'T GO OVER 35 MPH. MY 4WAS MOTOR HAS GONE BAD! INFINITI DEALERSHIP, CANNOT EXPLAIN WHAT WOULD HAVE CAUSED THE MOTOR, TO GO BAD. ALL OF THE CAR'S SAFETY FEAT...

UNKNOWN OR OTHER

Mar 2, 2019

INFINITI USES POOR QUALITY LEATHER AND VINYL IN THE INTERIOR OF THEIR CARS. THE LEATHER AND VINYL ON MY DOOR PANEL, CENTER CONSOLE, AND SEAT HAVE CRACKED. I AM VERY DISAPPOINTED WITH THE INTERIOR OF MY CAR. CONSIDERING THAT INFINITI IS A LUXURY AUTO MANUFACTURER, THE INTERIOR QUALITY IS APPAUDING. THIS WILL BE THE LAST...

UNKNOWN OR OTHER

Mar 2, 2019

THE LEATHER AND VINYL THAT IS INSTALLED ON THE INTERIOR COMPONENTS OF THE CAR ARE VERY POOR QUALITY. MY SEATS, DOOR PANEL, AND CENTER CONSOLE ARE CRACKING. THE INTERIOR OF MY CAR LOOKS TERRIBLE. CONSIDERING THAT INFINITI IS A LEISURE LINE AUTOMOBILE, IT IS APPALLING THAT THEY WOULD CUT CORNERS ON THE CAR'S INTERIOR BY...

Showing the 8 most recent of 36 complaints.

IMPORTANT INFORMATION

This report is compiled from official U.S. government vehicle-safety records (vehicle specifications, recalls, safety ratings and owner complaints) and is provided for informational purposes only. Missing values indicate the source has no data for that field - not that a feature is absent. Recall campaign summaries describe all vehicles within a campaign, not only this specific vehicle. This report is not a title/odometer history or a substitute for a professional inspection. Veri Vanta Auto is an independent service.



4501, Main Street Dallas, TX, 75201
sales@verivantaauto.com